


Wykreślić rzuty linii przenikania dwóch powierzchni walcowych obrotowych.



$$L1 \geq d2 + 20; L2 \geq d1 + 20$$

Nr	Zestaw	e	d1	d2
[-]	[-]	[mm]	[mm]	[mm]
1	I	10	40	30
2	I	10	40	35
3	I	10	40	40
4	I	10	40	45
5	I	10	40	50
6	I	10	45	30
7	I	10	45	35
8	I	10	45	40
9	I	10	45	45
10	I	10	45	50
11	I	10	50	35
12	I	10	50	40
13	I	10	50	45
14	I	10	50	50
15	I	10	50	55
16	II	10	40	60
17	II	10	40	65
18	II	10	40	70
19	II	10	40	75
20	II	10	40	80
21	II	10	45	65
22	II	10	45	70
23	II	10	45	75
24	II	10	45	80
25	II	10	45	85
26	II	10	50	70
27	II	10	50	75
28	II	10	50	80
29	II	10	50	85
30	II	10	50	90
31	II	10	55	75
32	II	10	55	80
33	II	10	55	85
34	II	10	55	90
35	II	10	55	95
36	II	10	55	100

Nr	Zestaw	e	d1	d2
[-]	[-]	[mm]	[mm]	[mm]
1	I	15	40	30
2	I	15	40	35
3	I	15	40	40
4	I	15	40	45
5	I	15	40	50
6	I	15	45	30
7	I	15	45	35
8	I	15	45	40
9	I	15	45	45
10	I	15	45	50
11	I	15	50	35
12	I	15	50	40
13	I	15	50	45
14	I	15	50	50
15	I	15	50	55
16	II	15	40	60
17	II	15	40	65
18	II	15	40	70
19	II	15	40	75
20	II	15	40	80
21	II	15	45	65
22	II	15	45	70
23	II	15	45	75
24	II	15	45	80
25	II	15	45	85
26	II	15	50	70
27	II	15	50	75
28	II	15	50	80
29	II	15	50	85
30	II	15	50	90
31	II	15	55	75
32	II	15	55	80
33	II	15	55	85
34	II	15	55	90
35	II	15	55	95
36	II	15	55	100